

U. S. Department of Agriculture

FOREST SERVICE

posted

Chippewa NATIONAL FOREST

G-21

CORNERS OF THE PUBLIC SURVEY

T. *59* R. *26.* *4th* Mer.

Section Corner common to Sections
....., and *11-12*

Corner consists of a *iron pin* (not) in place
State condition *Good*

Dimensions above ground *12"* inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<i>1/4 S</i>		<i>1/4 S</i>
	<i>11</i>		<i>12</i>
N	W	S	E

NW	SW	SE	NE

Mound of is located

..... Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species *Birch Birch*

Diameter *5 inches 6 inches*

Bearing *N. 10° W S. 5° E*

Distance *9 feet 11 feet*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

Walter Petroski

(Signature)

10/26/33
(Date)

Asst.
(Title)

Metal Location Poster is on a _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.
 Give any further facts which will aid in finding this Corner again.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer.

U. S. Department of Agriculture
FOREST SERVICE

G-21

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

1/4 Corner common to Sections

11, and 12
Corner consists of a 3" x 3" scribed Ironwood Post
3" x 1" 3-sided iron rod (not replace)

State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/4		1/4
	S 11		S 12
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 12	S 11		
T 59N	T 59N		
R 26W	R 26W		
B.T.	B.T.		

Species Birch stub W. Birch

Diameter 4" 5"

Bearing N18°E S4°W

Distance 15 Lks 29 Lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? records show it was set by

county surveyor.

Arthur Johnson
(Signature)

11/2/39

(Date)

Squad Foreman

(Title)

Corner again.

Give any further facts which will aid in finding this


*29 chains distant.

from which this Corner bears $N40^{\circ}E$

side of Tree

tree 5 inches diameter, on the North East

Metal Location Poster is on a W. Birch



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

CHIPPewa NATIONAL FOREST

G-21

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

1/4 Corner common to Sections

Corner consists of a 3" x 3" ~~scribed~~ ¹¹ Ironwood post ~~and~~ ¹² ~~set~~ ^(not in place) iron rod.

State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	1/4		
S 11			S 12

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 12
T 59N
R 26W

S 11
T 59N
R 26W

B.T.

B. T.

--

--

Species Birch stub. W. Birch

Diameter 4" 5"

Bearing N 180° S 40°

Distance 15 lks 29 lks

Do you believe this to be a genuine Land Office Corner? No

If not, why? records show it was set by

County Surveyor.

Arthur Johnson

(Signature)

Squad Foreman

(Title)

11/2/39

(Date)

T. 59 N R. 26 W Mer. 4 3

(Make sketch of topography near Corner)



Metal Location Poster is on a N. Birch tree 5 inches diameter, on the North East side of tree from which this Corner bears N40° E chains distant. Give any further facts which will aid in finding this Corner again.

U. S. Department of Agriculture

FOREST SERVICE

posted
G-21

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4th Mer.

2.14.1970 Corner common to Sections 11 and 12

Corner consists of a Post (not) in place
State condition None

Dimensions above ground 273" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>1/4</u>		<u>1/4</u>
	<u>511</u>		<u>12</u>

N

W

S

E

NW

SW

SE

NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1/2</u>	
<u>45</u>	

<u>1/4</u>	<u>11</u>
<u>15</u>	

<u>BT.</u>	
------------	--

--	--

<u>B.T.</u>	
-------------	--

--	--

Species Black Birch

Diameter 4" 4"

Bearing North, SW.

Distance 19 links, 28

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

(Signature)


(Date)

(Title)

Small tree by corner

Corner again.

Metal Location Poster is on a tree _____ inches diameter, on the _____ side of _____ from which this Corner bears _____ chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 57 R. 25 Mer.