

U. S. Department of Agriculture

FOREST SERVICE

F-21

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N. R. 26 W. 4th P Mer.

N 1/16

Corner common to Sections

Corner consists of a Aspen stake (not) in placeState condition GoodDimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N 1/16	N	N 1/16	N
5	1/16	5 1/16	1/16
11+12	5 11	12	5 12

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? NoIf not, why? U. S. F. S.

(Signature)

(Date)

(Title)

T.

R.

Mer.

(Make sketch of topography near Corner)

21 22 23

Sec. 12

Sec. 11

Sec.

Sec.

Metal Location Poster is on a *M. Birch*

tree *3* inches diameter, on the *East*

side of *tree*

from which this Corner bears *S 85 E*

0.30 chains distant.

Give any further facts which will aid in finding this

Corner again.

Poster on picket line