

U. S. Department of Agriculture  
FOREST SERVICE

2-22

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 R. 26 4 Mer.

W 1/16

Corner common to Sections

1, 2, 3, and 36

Corner consists of a Pine post (not) a place

State condition

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? U.S.F.S.

12-10-35

(Date)

*George H. Jennings*

(Signature)

*J. H. Newman S.M.*

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

23

from which this Corner bears

N10E


side of

tree

tree inches diameter, on the

N  
Aspen

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 59 R. 26 Mer. L.P.