

U. S. Department of Agriculture

FOREST SERVICE

F-25

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4 th Mer.

N 1/16

Corner common to Sections

12 - 59 - 26, and 7-59-25

Corner consists of a 3" Scribed Aspen Post in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N 1/16	N 1/16
S. 12	S. 7
N	W
S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

			Δ

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Records show it was set by County Surveyor.


Arthur Johnson
(Signature)

Squad Foreman
(Title)

11/7/39
(Date)

T. 59 N R. 26 W 4 th Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a
 tree inches diameter, on the
 side of
 from which this Corner bears
 chains distant.
 Give any further facts which will aid in finding this
 Corner again.

U. S. Department of Agriculture

FOREST SERVICE

F-25

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4 th Mer.

N 1/16

Corner common to Sections

12 - 59 - 26

7-59-25

and

Corner consists of a 5" Scribed Aspen Post in place

State condition Good

Dimensions above ground 38 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N 1/16		N 1/16					
8.12		S. 7					
N	W	S	E	NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No
Records show it was set by
County Surveyor.

Arthur Johnson

(Signature)

Squad Foreman

(Title)

11/7/39

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 59 N. R. 28 W. 4 1/2 Mer.

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

CHIPPEWA NATIONAL FOREST

F-25

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4 th Mer.

N 1/16

Corner common to Sections

12 - 59 - 26

7-59-25

, and

Corner consists of a 3" Scribed Aspen Post in place


State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **No**

If not, why? **Records show it was set by County Surveyor.**


Arthur Johnson
(Signature)

Squad Foreman

(Title)

11/7/39

(Date)



(Make sketch of topography near Corner)

T. 52 N. R. 36 W. 4th Mer.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.