

U. S. Department of Agriculture
FOREST SERVICE

John ...
E-1, 2

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 424 Mer.

MEANDER Corner common to Sections

_____, _____, 6, and 7
Corner ~~consists of a~~ not located (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>MC</u>			

Species CEDAR, dead stub

Diameter 7"

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

Walter W. Davis
(Signature)

7/13/35
(Date)

TECHNICAL FOREMAN
(Title)

U. S. Department of Agriculture
FOREST SERVICE

E-1,2

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 466 Mer.

MEANDER Corner common to Sections

_____, _____, 6, and 7
Corner ~~consists of~~ a (not located) (not) in place


State condition iron pipe in place 9/21/29 or 2

Dimensions above ground 5" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species CEDAR Birch Birch

Diameter 7" 7" 7"

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? YES


If not, why? _____

Walter H. Davis
(Signature)

2/13/35
(Date)

TECHNICAL FOREMAN
(Title)

Metal Location Poster is on a CEDAR (BT) tree 7" inches diameter, on the SOUTH side of BT from which this Corner bears 1/2 chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 4th Mer.

U. S. Department of Agriculture

FOREST SERVICE

Posted

CHIPPEWA NATIONAL FOREST

E-1,2

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 426 Mer.

MEANDER Corner common to Sections

_____, _____, and 6, and 7

Corner ~~consists of a~~ not located (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>MC</i>			

Species CEDAR

Diameter 7"

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **YES**

If not, why? _____

Walter W. Davis

(Signature)

TECHNICAL FOREMAN

(Title)

2/13/35

(Date)

Corner again.


Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of B.T.

tree 7" inches diameter, on the SOUTH

Metal Location Poster is on a CEDAR (B.T.)



(Make sketch of topography near Corner)

T. 59 N. R. 26 W. 4th Mer.