

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST G-H-13

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th P Mer.

M C Corner common to Sections
9, and 10

Corner consists of a (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	MC		MC
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	BT		BT

Species Cedar (white) Cedar (white)

Diameter 6" 6"

Bearing S20°W S45°E

Distance 56 ch 40 ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

George W. Jennings
(Signature)
7-30-35
(Date)
Const. Foreman C & M
(Title)


Corner again.
Poster is in small clump
of cedar. Trail 2 chs. So.

Give any further facts which will aid in finding this
D#2 chains distant.

from which this Corner bears
side of tree
N 55 W

tree 10 inches diameter, on the
NW

Metal Location Poster is on a
W Cedar



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th P Mer.

U. S. Department of Agriculture

FOREST SERVICE

GH-137

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4th P Mer.

M C

9

Corner common to Sections

10

Corner consists of a (not) a place



State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Cedar (dead&Down) Cedar (dead

Diameter 6" 6"

Bearing S20°W S45E

Distance .56 ch .40ch

Do you believe this to be a genuine Land Office Corner Yes

If not, why?

George H. Jennings

(Signature)

Const, Foreman C & M

7-30-35

(Date)

(Title)

cedar. Trail 2 chs. So.
Poster is in small clump of

Corner again.

Give any further facts which will aid in finding this


0.42 chains distant.

from which this Corner bears N55W

side of tree

tree 10 inches diameter, on the NW

Metal Location Poster is on a W. Cedar



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

G, H-13

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59th R. 26th Mer.

me Corner common to Sections
9, _____, and 10

Corner consists of a Rock (not) in place

State condition good

Dimensions above ground Round - 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? 0

If not, why? _____

Mar 31 1936

(Date)

(Signature)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.5-57

from which this Corner bears


3-27 E

side of

tree 4 inches diameter, on the

corner

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. R. Mer.