

camp copy

U. S. Department of Agriculture
FOREST SERVICE

LM-25

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

Meander Corner common to Sections
13, , and 18

Corner consists of a 4" Post (not) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Aspen Birch

Diameter 6 5

Bearing S34°30' W S31°30' E

Distance 22 lks 32 lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? County scribing on Post and bearing trees

Murbach + Niebuhr
(Signature)

1/6/37
(Date)

(Title)

Corner is approx. 5 chains
north of Clark House & 700 feet
road

Corner again.

Give any further facts which will aid in finding this


22 links ~~other~~ distant.

from which this Corner bears N 34° 30' E

side of tree

tree 6 inches diameter, on the north

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 59 R. 26 Mer. 4d