

U. S. Department of Agriculture

FOREST SERVICE

ST-13

Chippewa NATIONAL FOREST

Posted. ST-13

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

M. C. Corner common to Sections
27, and 28Corner consists of a 3" SPRUCE (red) in place
State condition good

Dimensions above ground 2' 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S 28		S 27
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

	S 28		S 27
	B.T		B.T

Species B. spruce B. Spruce

Diameter 8" 6"

Bearing N 23° W N 12° E

Distance 55 Lk 44 Lk

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Emin Meagher
(Signature)1-3-35
(Date)Field Ass't
(Title)

Corner again.


Give any further facts which will aid in finding this

~~47~~ ⁴⁷ ~~mi.~~ ^{mi.} ~~cross~~ ^{cross} distant.

from which this Corner bears S 12° W

side of tree

Metal Location Poster is on a B. Spruce tree 6 inches diameter, on the S. W.



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th Mer.