

U. S. Department of Agriculture
FOREST SERVICE

T-9, 10

Chippewa NATIONAL FOREST

Posted

T-9, 10

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

M. C. Corner common to Sections
28, and

Corner consists of a 4" cedar (not) in place

State condition good (1" iron pipe 6")

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species	W. Birch	W. Birch
Diameter	4"	5"
Bearing	N 76° E	S 53° E
Distance	47 Li	23 Li

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

Erwin Meagher

(Signature)

Field ass't


(Title)

1-8-35

(Date)

Corner again.
The BITS and corner posts
are NOT described
LAND ROLLING SECOND
grow with W. Birch

Metal Location Poster is on a
tree 6 inches diameter, on the
side of tree
from which this Corner bears
23.71 chains distant.
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th Mer.