

U. S. Department of Agriculture
FOREST SERVICE

TU-13

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

AA, C. Corner common to Sections
27, and 28



Corner consists of a 3" Spruce (not) in place
State condition good

Dimensions above ground 2' 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species B. Spruce B. Spruce

Diameter 8" 6"

Bearing N. 23° W N. 12° E

Distance 55 Li 44 Li

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

Emin Meagher
(Signature)

1-3-35

(Date)

Field Ass't

(Title)

Corner again.

Give any further facts which will aid in finding this


49 L. ~~feet~~ distant.

from which this Corner bears S 12° W

side of tree

tree, 6 inches diameter, on the S. W

Metal Location Poster is on a B. S. Spruce



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th Mer.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

Posted TU
13

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 26 W 4th Mer.

M. C. Corner common to Sections
27, and 28

Corner consists of a 3" ASPEN (not) in place
State condition good

Dimensions above ground 2' 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---|----|---|----|
| | S | | S |
| | 28 | | 27 |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| | | | |
| NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|-----|--|-----|
| | S | | S |
| | 28 | | 27 |
| | B.T | | B.T |

Species Cedar Cedar

Diameter 1 1/4" 6"

Bearing N 68° W N 35° E

Distance 11 Li 17 Li

Do you believe this to be a genuine Land Office Corner? yes


If not, why? _____

Emin Meagher
(Signature)

Field Ass't
(Title)

1-3-35
(Date)

Metal Location Poster is on a Cedar tree 1 1/4 inches diameter, on the S. E. side of tree from which this Corner bears 1177 ~~ft~~ distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 59 N R. 26 W 4th Mer.