

U. S. Department of Agriculture  
FOREST SERVICE

R-13

*Chippewa* NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. *29 N* R. *27 W* *4<sup>th</sup>* Mer.



*S* Corner common to Sections  
*21, 22, 27, and 28*

Corner consists of a *post* (not) in place  
State condition *decayed*

Dimensions above ground *down* inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_  
Diameter \_\_\_\_\_  
Bearing \_\_\_\_\_  
Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *ye*  
If not, why? \_\_\_\_\_

*Paul Nelson*  
(Signature)

*2-11-35*  
(Date)

*C. C. Enos*  
(Title)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


chains distant. **009**

from which this Corner bears **N 65 W**

side of **tree**

tree **6** inches diameter, on the **NW**

Metal Location Poster is on a **Postmark**



(Make sketch of topography near Corner)

R-13

Mer. **428**

T. 09N R. 27W

U. S. Department of Agriculture  
FOREST SERVICE

R-13

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 59N R. 27W 4th Mer.

S Corner common to Sections  
21, 22, 27, and 28

Corner consists of a post (not) in place

State condition Decayed

Dimensions above ground down inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Paul Nelson  
(Signature)

CCC Enrolllee  
(Title)

2-11-35  
(Date)

Corner again.

Give any further facts which will aid in finding this

0.09 chains distant.

from which this Corner bears N 65 W


side of

Tree

tree 6 inches diameter, on the

N W

Metal Location Poster is on a *Beam*



(Make sketch of topography near Corner)

R-13

Mer.

42

T. 59 N R. 27 W

U. S. Department of Agriculture

FOREST SERVICE

*Posted*

*C. Chapman* NATIONAL FOREST *R13*  
CORNERS OF THE PUBLIC SURVEY

T. *29N* R. *27W* *9th* Mer.

*5* Corner common to Sections  
*21, 22, 27, and 28*

Corner consists of a *post* (not) in place  
State condition *decayed*

Dimensions above ground *down* inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*Paul Nelson*  
(Signature)

*2-11-25*  
(Date)

*C. C. Envallee*  
(Title)

Corner again.

Give any further facts which will aid in finding this

0.09 chains distant.

from which this Corner bears

N 65° W

side of


Tree

tree 6 inches diameter, on the

N 20° W

Metal Location Poster is on a

Postmark



(Make sketch of topography near Corner)

T. 59N R. 27W

4th Mer.

R-13