

U. S. Department of Agriculture
FOREST SERVICE

X-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N., R. 27 W., 4th Mer.

1/4

Corner common to Sections

33, and 34

Corner consists of a Iron pipe (not) in place

State condition Good

Dimensions above ground 5 inches inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|----------|--|--|--|
| 1/4 S | | | |
| BT | | | |

Species Norway

Diameter 9"

Bearing N 85°30' W

Distance 40 links

Do you believe this to be a genuine Land Office Corner? _____

If not, why? Set by Knoblauch using above bearing and distance from original B. T. as given in original GLO notes

C. J. Knoblauch
C. J. Knoblauch

(Signature)

Aug. 19, 1936

Assistant Ranger

(Date)

(Title)

The corner is marked with a 3" cedar stake, painted white, extending 2 feet above ground.

Corner is located 2 ebs. South of white post with Form 458-a on it beside the truck trail beginning at SE corner of Sec 12-148-25 and bearing SE.
Corner again.

Give any further facts which will aid in finding this

chain's distant.


6 links

from which this Corner bears N 80° E

side of the tree

tree 38 inches diameter, on the West

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 59 N., R. 27 W., 4th Mer.

U. S. Department of Agriculture
FOREST SERVICE

Chippewa

NATIONAL FOREST

X 13

CORNERS OF THE PUBLIC SURVEY

T. **59** N., R. **27** W., **4th** Mer.

1/4

Corner common to Sections

33

, and

34

Corner consists of a **Iron pipe** (not) in place

State condition **Good**

Dimensions above ground **5 inches** inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|---|---|---|---|
| | | | |
| N | W | S | E |

| | | | |
|----|----|----|----|
| | | | |
| NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|----------|--|--|--|
| 1/4 S | | | |
| 87 | | | |

Species **Norway**

Diameter **9"**

Bearing **N 85°30' W**

Distance **40 links**

Do you believe this to be a genuine Land Office Corner? _____

If not, why? **Set by Knoblauch using above bearing and distance from original B. T. as given in original GIO notes**

C. J. Knoblauch
C. J. Knoblauch

(Signature)

Aug. 19, 1936

(Date)

Assistant Ranger

(Title)

above ground.

The corner is marked with a 3" cedar stake, painted white, extending 2 feet

Sec 12-148-25 and bearing SE.

Truck trail beginning at SE corner of post with form 458-a on it beside the corner is located 2 chs. South of white

Corner again.

Give any further facts which will aid in finding this


8 links from which this corner bears

N 60° E

side of

tree inches diameter, on the West

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

T. 59 N., R. 27 W., 4th Mer.

AUG 20 1936

RECEIVED