

U. S. Department of Agriculture
FOREST SERVICE

V-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 27W ²⁶ 4 Mer.

Sec. Corner common to Sections
30, 31, 25, and 36

Corner consists of a 4" B. Spr. (rod) in place

State condition good 1" iron pipe

Dimensions above ground 24" 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

S	S		
25	36		

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____ NO B.Ts

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Ervin Meagher

(Signature)

Field Ass't


(Title)

10-1-35

(Date)

CORNER IS ON ALDER DITCH
BANK. NO TREES WITHIN
SUITABLE DISTANCE
FOR LOCATION POSTER
Corner again.

Give any further facts which will aid in finding this
chain's distant.
from which this Corner bears
side of
tree inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 59 N R. 27 W 4 V-25 Mer.