

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 26-27 4 Mer.

Sec. Corner common to Sections  
6, 7, 1, and 12

Corner consists of a Post set (not) in place

State condition Bad

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

\_\_\_\_\_ Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T60 R26 7			
BT	BT		

Species Tam Tam

Diameter 11" 14"

Bearing S78°W N25°W

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? Does not check with G. L. O.

W. J. Dayle

(Signature)


Estimator

(Title)

10/23/23  
(Date)

Corner again.  
West Port Warr Sec. 6 + 7 corner  
154 845 IN SWAMP

Metal Location Poster is on a  
tree inches diameter, on the  
side of  
from which this Corner bears  
chains distant.  
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 50 R. 26 Mer. 4

U. S. Department of Agriculture

FOREST SERVICE

*posted  
E-1*

CHIPPENAW NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 26 Mer. 60-274

Section 6, 7, 8 Corner common to Sections 6, 7, 8 and 12 of 60-274

Corner consists of a Post (Set) (not) in place



State condition Bad

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of  is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 100  
R 24  
S  
7



BT

BT



Species TAM TAM

Diameter 11 14

Bearing S 67 BW N 25 W

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

11-73-1933


(Date)

*W. G. ...*  
(Signature)

(Title)

Corner again.  
Running West of Johnson  
Location lot 7 I. H. Johnson  
at farm Mrs. M. M. Johnson

Metal Location Poster is on a  
tree \_\_\_\_\_ inches diameter, on the  
side of \_\_\_\_\_  
from which this Corner bears  
\_\_\_\_\_ chains distant.  
Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 60 R. 26 N. 4 Mer.