

U. S. Department of Agriculture  
FOREST SERVICE

R-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 N. R. 26 W 4<sup>th</sup> P. Mer.

Section Corner common to Sections  
20, 21, 28, and 29

Corner consists of a Scribed post (not) in place  
and Iron pp.  
State condition Good

Dimensions above ground 36 post 3 Iron inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

F.S. Poster			

Species W. Pine \_\_\_\_\_

Diameter 10" \_\_\_\_\_

Bearing S49°W. \_\_\_\_\_

Distance 20 \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Established by County

and County work in Sections

North and East tied to it.

J. A. Gelhaus

(Signature)

Sr. Civil Eng

(Title)

6/28/37  
(Date)



U. S. Department of Agriculture  
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 60 N R. 26 W 4th Mer.

Section Corner common to Sections

20, 21, 28, and 29

Corner consists of a wooden stake (not) in place

State condition Found

Dimensions above ground Dia - 3", Hgt. - 36" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S. 20	S. 29	S. 28	S. 21
-------	-------	-------	-------

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

obliterated			
B.T.			

Species Wh. Pine \_\_\_\_\_

Diameter 12" \_\_\_\_\_

Bearing S 49° W \_\_\_\_\_

Distance 194 \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

J. H. Moore

(Signature)

July 5, 1924

(Date)


Tech. Foreman

(Title)

-----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----  
 -----

Corner again.  
 corner is on ridge  
 east + west.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60N R. 36W 4th P Mer.

Section 20 Corner common to Sections 21, 28 and 29

Scribed post &

Corner consists of a Iron pipe (not) in place

State condition Good

Dimensions above ground Post 36 Iron 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

128



Species P. Pine

Diameter 10"

Bearing S49°W

Distance 20

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Established by County and County work in sections North and East tied to it.

J. A. Gielhaug

(Signature)

Jr. Civil Eng.

6/28/37

(Date)

(Title)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


0.45 chains distant.

from which this Corner bears N49° E

side of tree

tree 10 inches diameter, on the NE

Metal Location Poster is on a W. Pine



(Make sketch of topography near Corner)

T. 60N R. 26W 4th P Mer.