

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

R-15

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 26 Mer. 4

1/4 Corner common to Sections
22, 27, and _____



Corner consists of a Norway Pine (not) in place
State condition living; blazed on 2 sides

Dimensions above ground 40'

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter None

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Too uncertain. However line run from corner checked in closely with a known corner 1 mile distant

J. Moore per H. G. Altman
(Signature)

12/16/34
(Date)

Tech. Foreman
(Title)


Corner again.
 Stake put in ground by lines
 survey party

Give any further facts which will aid in finding this
 chains distant.

From which this Corner bears $S 70^{\circ} E$
 $\frac{15}{100}$

side of ~~the~~

Metal Location Poster is on a *Murray* *Drill*
 tree 7 inches diameter, on the *bank*



(Make sketch of topography near Corner)

T. 60 R. 26 # Mer.