

U. S. Department of Agriculture
FOREST SERVICE

E-17

Posted

CHIPPEWA NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 60N R. 26W 4TH Mer.

SECTION Corner common to Sections
2, 3, 10, and 11

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>52</u> <u>T60</u> <u>R26</u>	<u>511</u> <u>T60</u> <u>R26</u>	<u>510</u> <u>T60</u> <u>R26</u>	
<u>BT</u>	<u>BT</u>	<u>BT</u>	

Species WHITE SPURGE BALSAM BALSAM STUB
Diameter 14" 10" 12"
Bearing N17E S25W S48W
Distance .43CH 1.26CH 2.26CHS.

Do you believe this to be a genuine Land Office Corner? Yes.


If not, why? _____

Ralph L. Johnson
(Signature)
November 6, 1934
(Date) Cons. Foreman
(Title)

.....
.....
.....
.....
.....

Corner again. DISTANCES
BENCHES GIVEN FOR BTS
ARE FROM TELEPHONE
POLE TO BT

Give any further facts which will aid in finding this
... UNKNOWN chains distant. CORNER ON ROAD &
from which this Corner bears UNKNOWN
side of POLE
... 6. inches diameter, on the SOUTH
Metal Location Poster is on a TELEPHONE POLE



(Make sketch of topography near Corner)

T. 60N R. 26W 4TH Mer.

U. S. Department of Agriculture

FOREST SERVICE

E-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 26 Mer.

Section Corner common to Sections

2, 3, 10, and 11

Corner consists of a _____ (not) in place

State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S2 T60 R26	S11 T60 R26	S10 T60 R26	
BT	BT	BT	

Species Wt. Spr. Bol. Bol. Stob

Diameter 14" 10 1/2" 12"

Bearing N17E S25N S48N } See over

Distance 43 1.26 2.26

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Corner must have been located by later survey as it does not check with G.L.O.


R. R. Johnson
(Signature)

Nov 6, 34
(Date)

C.F.
(Title)

The bearings & distance
 given (are) are from the telephone
 pole to the B.T. Corner would
 be in road.
 Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears unknown
 side of
 tree inches diameter, on the S. of road
 Metal Location Poster is on a Telephone Pole




(Make sketch of topography near Corner)

T. Co. R. 26 Mer. X

<u>Co.</u>	<u>Lat Trees</u>	<u>Bear</u>	<u>Dist</u>
25-340-11	Balsam	N 41 E	92.0
(60-26)	Stb	7" S 33 E	99.6
	Red Bear Spruce	8" N 61 1/2 W	106.3
	Aspen	9" S 40 E	67.9
	Ash	4 S 28 W	122.9

E-17



Office Memorandum

TO :

FROM :

SUBJECT:

Verg. Perhaps
for further Ref

