

U. S. Department of Agriculture

FOREST SERVICE

P-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60N R. 26W 4th P. Mer.

Quarter Corner common to Sections

23, and 26

Corner consists of a Scribed Post (not) in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

079 BT

<u>1/4</u> <u>S 26</u>	
---------------------------	--

Mild. New.

<u>1/4</u> <u>S 23</u>	
---------------------------	--

<u>BT.</u>	
------------	--

<u>BT.</u>	
------------	--

Species N. Pine. Sp.

N. Pine

Diameter 22"

6"

Bearing S 24° E.

N. 52° W. N 52° W.

Distance 4

15 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

J. A. Gjelhaug

(Signature)

Jr. Civil Eng.


(Title)

7/17/37

(Date)

(Make sketch of topography near Corner)

T. 60N R. 26W 4th P. Mer.



Metal Location Poster is on a *N. 17th*

tree *6* inches diameter, on the *S.E.*

side of *tree*

from which this Corner bears *S 52° E*

0.15 1/2 chains distant.

Give any further facts which will aid in finding this

Corner again.

U. S. Department of Agriculture

FOREST SERVICE

Chippewa National Forest

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60N R. 26W Mer.

Quarter Corner common to Sections

23 and 26


Corner consists of a 2x18 in. ir. pipe (not) in place State condition Good

Dimensions above ground 40 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. BT

S 26



B.T.

Mkd. New

S 23



B.T.

Species N. Pine, Stp. N. Pine

Diameter 22" 6"

Bearing S24° E N52° W

Distance 4 15 1/2

Do you believe this to be a genuine Land Office Corner?

If not, why?

J. A. Gielhaug

(Signature)

7/17/37


(Date)

Jr. Civil Eng.

(Title)

(Make sketch of topography near Corner)

T. 60N R. 26W 4th P Mer.



Metal Location Poster is on a N. Pine

tree 6 inches diameter, on the SE

side of tree

from which this Corner bears $552^{\circ} E$

0.157 chains distant.

Give any further facts which will aid in finding this

Corner again.