

U. S. Department of Agriculture
FOREST SERVICE

2-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 5960 N R. 26 W 9th Mer.

Section Corner common to Sections
1, 2, 35, and 36

Corner consists of a 2" Approx. Post (not) in place
State condition Good

Dimensions above ground 29 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

5.2
T59N
R26W

--

--

--

BT

--

--

--

Species Maple _____

Diameter 12" _____

Bearing S25°W _____

Distance 30 lks _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Arthur T. Johnson

(Signature)


Squad Foreman

(Title)

2/5/40

(Date)

(Make sketch of topography near Corner)



Metal Location Poster is on a

tree _____ inches diameter, on the

side of _____

from which this Corner bears _____

chains distant.

Give any further facts which will aid in finding this

Corner again.

This corner lies 3.50 chains East
of N. # 602

T. 59460N R. 26W 916 Mer.