

**U. S. Department of Agriculture**  
**FOREST SERVICE**

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 60 N R. 26 W 4<sup>th</sup> Mer.

1/4 Corner common to Sections  
....., ....., 11, and 12

Corner consists of a 3" Cedar Post 1/2 x 1/2 x 5' (not) in place  
State condition Good

Dimensions above ground 30 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

**CARDINAL POSITION**

**DIAGONAL POSITION**

--	--	--	--

N      W      S      E

--	--	--	--

NW    SW    SE    NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species Birch stub Spruce stump

Diameter 10" 12"

Bearing W E 38° S

Distance 34 lks. 30 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? .....

Musbeck - Niebuhr

(Signature)

9-14-36


(Date)

Sy. F. R. Clerks

(Title)

Corner again.  
 Spruce stump rotted, minerals barely visible, Birch stub decayed, no minerals visible.  
 Area around corner post, dead balsam + birch snags, burnt over Area.  
 Stream approx. 3chs west of corner post.  
 To find corner post, from strike place follow old trail.

Give any further facts which will aid in finding this  
 53 links ~~chain~~ distant.  
 from which this Corner bears W 13° 50  
 side of Tree  
 tree 8 inches diameter, on the East  
 Metal Location Poster is on a Birch



(Make sketch of topography near Corner)