

U. S. Department of Agriculture

FOREST SERVICE

5-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 N. R. 26 W. 4th Mer.

4 Section Corner common to Sections

12, and 13

Corner consists of a W. Birch stake (not) in place



State condition Good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION



DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Birch

Diameter 9"

Bearing North

Distance 16 Lks

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

E. O. Fredrickson

(Signature)

Forester (Admin)

2-3-55

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

16 chains distant.

From which this Corner bears

South

side of


it

tree 9 inches diameter, on the

South

Metal Location Poster is on a

W. Birch B.T.



(Make sketch of topography near Corner)

T. CORN R. 26W 45P Mer.