

U. S. Department of Agriculture

FOREST SERVICE

2-25 P

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 N 61 R. 26 4 Mer.

Section 7 Corner common to Sections

36, 37, 2, and 1

Corner consists of a T 61 T 60 (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Cardinal position sketch grid with columns N, W, S, E

N W S E

Diagonal position sketch grid with columns NW, SW, SE, NE

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Sketching boxes for trees, with handwritten 'T 60 R 26 S 1 C 6' and 'X' in the first box.

Species T. m.

Diameter 11"

Bearing S 17 1/2 E

Distance .06 ch.

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

G. L. Finney

(Signature)

7/31/35

(Date)

Jr. Forester

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.


130

from which this Corner bears N 17° 45' E

side of *CORNER*

tree 10 inches diameter, on the *NE*

Metal Location Poster is on a *Black Spruce*



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

N-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 & 60 N R. 25 & 26 W 4th Mer.

TWP. Corner common to Sections

1-59-26, 6-59-25, 31-60-25, and 36-60-26

Corner consists of a 2" Iron pipe with Cap. (not) in place


State condition Good

Dimensions above ground Post 30 Pipe 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



5.86	51	5.6	5.31
T60N	T59N	T59N	T60N
R26W	R26W	R25W	R25W
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

5.1 T. 59 N R. 26 W			
BT			

Species R. Pine. Stub

Diameter 19"

Bearing S35°W

Distance 151ks

Do you believe this to be a genuine Land Office Corner? No

If not, why? Set by County from G. L. O.


Be T's one of which remains

Arthur J. Johnson
(Signature)

Special Foreman
(Title)

3/19/90
(Date)

(Make sketch of topography near Corner)



Metal Location Poster is on a *Dead W. Pine*

tree *20* inches diameter, on the *N.W.*

side of *Trees*

from which this Corner bears *N 60° W*

.79 chains distant.

Give any further facts which will aid in finding this

Corner again.

T. 59460N R. 25726W 9th Mer.