

U. S. Department of Agriculture  
FOREST SERVICE

*N-25*  
*N-1 Posted*

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *60N.* R. *25 & 26W* *4<sup>th</sup>* Mer.

*Section* Corner common to Sections

*18, 19, 23, and 24*

Corner consists of a *Wood stake* in place

State condition *Decaying*

Dimensions above ground *Dia-3"; Hgt-36"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S. 13	S. 24	S. 19	S. 18
-------	-------	-------	-------

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>Obliterated</i>	S. 24	<i>Obliterated</i>	

Species *Tam. Spruce Spruce*

Diameter *4" 5" 4"*

Bearing *N 25° E N 45° W S 35° E*

Distance *10 20 30*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*L. H. Moor*  
(Signature)

*June 26, 1934*  
(Date)

*Field Foreman*  
(Title)

-----

-----

-----

-----

-----

-----

-----


-----

-----

-----

Corner again.

Give any further facts which will aid in finding this  
 ----- chains distant.  
 ----- from which this Corner bears  
 ----- side of  
 ----- tree ----- inches diameter, on the  
 ----- Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 60 N. R. 25 & 26 W. 4th Mer.