

U. S. Department of Agriculture
FOREST SERVICE

7-24-25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 26 4 Mer.

Meander Corner common to Sections
....., 1, and 12

Corner consists of a (not) in place

State condition No stake found

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>61 11</u>

<u>62 512</u>

--

--

<u>BT</u>

<u>BT</u>

--

--

Species Aspen Aspen

Diameter 10" 10"

Bearing N 61 W S 24 N

Distance 10 ch 08 ch

Do you believe this to be a genuine Land Office Corner?

~~Yes~~, why? Bearing trees check with original notes

H. Bergstrom

(Signature)

10/11/34

(Date)

ccc

(Title)

Corner again.

Give any further facts which will aid in finding this

10 chains distant.


from which this Corner bears *N 61 W*

side of *Corner*

tree *14* inches diameter, on the *NW*

Metal Location Poster is on a *Aspen*

60/26 *60/25*



(Make sketch of topography near Corner)