

**U. S. Department of Agriculture**  
**FOREST SERVICE**

----- NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 60 N R. 26 W 4th Mer. D  
1-2

S 1/6th Meander Corner common to Sections  
19 (60/136) & 24, and (60/27)

Corner consists of a Cedar Post (not) in place

State condition Good

Dimensions above ground 3x3 x 2 1/2" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	M.C.		M.C.
	1/16		1/16
	Cor		Cor


N      W      S      E

NW   SW   SE   NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species No bearing trees

Diameter -----

Bearing -----

Distance -----

Do you believe this to be a genuine Land Office Corner? -----

If not, why? -----

Leo I. Kaja  
(Signature)

(Date)


(Title)

T.

R.

Mer.

(Make sketch of topography near Corner)



Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.

On Bello Lake