

U. S. Department of Agriculture
FOREST SERVICE

N 3-4

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 59N-60N R. 26W 4th Mer.

Monter Corner common to Sections
_____, _____, 31, and 6

Corner consists of a Wooden post () in place
State condition Good

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Mc		Mc	
56		56	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Mc			
56			

Species Aspen Birch
Diameter 8" 4"
Bearing S83°W N32°E
Distance 224 254

Do you believe this to be a genuine Land Office Corner? No

If not, why? Stake indicates age to be about 10 yrs old line blazes quite recent.

[Signature]
(Signature)

Feb 7, 1935
(Date)

Technical Foreman
(Title)

Shore

Meander corner on lake
Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this corner bears *N 83° E*

side of *tree*

tree *8"* inches diameter, on the *East*

Metal Location Poster is on a *fisher*



(Make sketch of topography near corner)

T. 57N. 60N. R. 26W. 444 Mer.