

Form 974-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

5-11-13

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 21 4 Mer.

S 116 Corner common to Sections
15, and 16

Corner consists of a stake (not in place)

State condition good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? no

If not, why? _____

Established by Enrollees


H. Kamalain
(Signature)

12-18-39
(Date)

cee
(Title)

Corner again:
Corner located East of Hwy # 6 approx. 1200 ft. N.E. of Hwy # 6.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)