

U. S. Department of Agriculture

FOREST SERVICE

Previously Posted
CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 27 4TH Mer.

Corner common to Sections

34, 35, 26, and 27

Corner consists of a original stake (out) in place

State condition Good

Dimensions above ground 2 FT. inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

T60N	T60N	T60N	T60N
R27S	R27S	R27S	R27S
Sec.	Sec.	Sec.	Sec.
27	34	35	26

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Sec. 27	Sec. 34	Sec. 35	
---------	---------	---------	--

B.T.	B.T.	B.T.	
------	------	------	--

Species N.P. ST N.P. ST N.P. ST

Diameter 11 in 12 in 14 in

Bearing 30° W of N 50° S of W 10° S of E

Distance 1.5 H 40 LKS 130 LKS

Do you believe this to be a genuine Land Office Corner? No

If not, why? The stake does not look old enough and the B.T. are stumps not trees

(S) Orville Hatt

(S) W. A. Maddy

(Signature)

Estimator

11/6/33

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. 60

R. 27

1174

Mer.

V-17