

U. S. Department of Agriculture
FOREST SERVICE

R-23

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 60 R. 27 Mer.

^{1/4} Corner common to Sections
24, 25, and



Corner consists of a Scrubbed post (not) in place
State condition Fair

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tan Dead - 15' st. b

Diameter 8"

Bearing N89E

Distance 128.143

Do you believe this to be a genuine Land Office Corner? No

If not, why? Presurvey

Ralph H. Christensen
(Signature)

(Signature)


D. F. P.

(Title)

1-3-56
(Date)

Corner again.
 Post is in center of *60-0-00*
 road across slope about 12' SW
 of post. Fence corner about 15' East.

Metal Location Poster is on a *None* tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)