

U. S. Department of Agriculture  
FOREST SERVICE

2-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 61N R. 26W 4th E. Mer.

1/4 Correction Corner common to Sections

32

Corner consists of a Aspen post & Iron pin in place



State condition Good

Dimensions above ground post 3 x 3 x 30 inches  
pin 1 x 6

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? No BT's found, but corner was evidently reestablished from them several years ago

*[Handwritten Signature]*

(Signature)

Jr. Asst. to Tech.


(Title)

3-23-38

(Date)

Give any further facts which will aid in finding this Corner again.  
Slide line brushed out North from cor.

Metal Location Poster is on a Aspen  
tree 5 inches diameter, on the Southeast  
side of Fence corner  
from which this Corner bears  
0.23 chains distant.



(Make sketch of topography near Corner)