

U. S. Department of Agriculture
FOREST SERVICE

Z-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 61N R. 26W 4th P. Mer.

section correction Corner common to Sections
....., 32, and 33

Corner consists of a Aspen post (~~rock~~) in place
State condition good

Dimensions above ground 4 x 4 x 30 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

S 32			S33 T61N R26W
NW	SW	SE	NE

Mound of is located

..... Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S33	S32	T61N R26W S32	
BT	BT	BT	T

Species Bal. Stp Birch Bal. stp. R. Pine Stp.
Diameter 2 16^{stp} 10 28
Bearing S65°30'E N69°W N44°W N37 E
Distance 0.13ch 0.28ch 0.43ch 0.22ch

Do you believe this to be a genuine Land Office Corner? Yes


If not, why? No trace found of original BT's
as shown by GIO notes. However, BT's
are very old.

LeRoy Peterson
.....
(Signature)

3/22/58
.....
(Date)

Jr. Asst. to Tech.
.....
(Title)

(Make sketch of topography near Corner)



Metal Location Poster is on a **Balsam**

tree **6** inches diameter, on the

side of

from which this Corner bears

S88° E

0.13

chains distant.

Give any further facts which will aid in finding this

Corner again.

Line blazed east from corner to High-

way. Line cut and blazed west from

corner.