

Form 874-D—Revised May, 1913
U. S. Department of Agriculture
FOREST SERVICE

K1

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 25 S Mer.

#3 1/16

Corner common to Sections

18, and 19

Corner consists of a post in place



State condition GOOD

Dimensions above ground 16" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species None

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Corner

Raymond T. DeFaut
RAYMOND T. DEFANT

(Signature)

Jr. Civil Engineer

(Title)

1-2-40

(Date)

Post sets 25 links east of center line of road on ditch bank

Corner again.

Give any further facts which will aid in finding this

chains distant.

S 60° E

from which this Corner bears

Corner


side of

N.W.

tree 5 inches diameter, on the

Metal Location Poster is on a

Ash



(Make sketch of topography near Corner)

R-1