

Form 874-3—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

75

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 25 S. 5 Mer.

1/4 Corner common to Sections
29, 30, and 30

Corner consists of a _____ (not) in place
 State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 29			
B T			

Species Cedar stump

Diameter 8"

Bearing S 80 E

Distance 14

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

R. Defant

(Signature)

J. E.

(Title)

7-2-40

(Date)

SECTION 30

Corner again
Give any further facts which will aid in finding this
chains distant.

38

Part from which this Corner bears


side of

Road

tree inches diameter, on the

West

Part Metal Location Poster is on a



(Make sketch of topography near Corner)