

U. S. Department of Agriculture
FOREST SERVICE

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

Section _____ Corner common to Sections

_____, 30, and 31

Corner consists of a pipe ~~(XXX)~~ in place

State condition good ~~poor~~

Dimensions above ground in road ~~good~~ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **NO**

If not, why? County Corner

R. T. Defant
RAYMOND T. DEFANT

(Signature)

Jr. Civil Engineer

7-3-40

(Date)

(Title)

Corner again. pipe has been removed by road crew.


Give any further facts which will aid in finding this
31 chains distant.

from which this Corner bears west

side of road

tree inches diameter, on the East

post Metal Location Poster is on a



(Make sketch of topography near Corner)