

U. S. Department of Agriculture

FOREST SERVICE

0-1

12/14/40

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

1/4 Corner common to Sections 6, and

Corner consists of a brass cap (not) in place State condition poor

Dimensions above ground loose inches Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Grid for cardinal positions: N, W, S, E

Grid for diagonal positions: NW, SW, SE, NE

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Grid for sketching bearing trees and rocks

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? yes

If not, why?

R. T. Defant Raymond T. Defant

(Signature)

Jr. Civil Engineer

(Title)

7/30/40

(Date)

101

2294


Corner again.  
corner found out of ground not near  
large post

Give any further facts which will aid in finding this  
chains distant.

from which this Corner bears

side of  
tree inches diameter, on the  
rod

Metal Location Poster is on a  
post



(Make sketch of topography near Corner)