

U. S. Department of Agriculture  
FOREST SERVICE

E-3  
POSTED  
12/11/18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

1/2 Corner common to Sections  
6, and 7

Corner consists of a brass cap ~~rock~~ in place  
State condition good

Dimensions above ground 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<b>S</b>		<b>S</b>	
<b>6</b>		<b>7</b>	
<b>N</b>	<b>W</b>	<b>S</b>	<b>E</b>

<b>NW</b>	<b>SW</b>	<b>SE</b>	<b>NE</b>

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? **yes**


If not, why? \_\_\_\_\_

*R. T. Rowen*  
Don. Rowen  
(Signature)

**Ass't Leader**  
(Title)

**8/23/40**  
(Date)

Metal Location Poster is on a ~~corner post~~  
 tree ~~2~~ inches diameter, on the ~~west~~  
 side of ~~post (corner beside post)~~  
 from which this Corner bears  
 chains distant.  
 Give any further facts which will aid in finding this  
 Corner again.



(Make sketch of topography near corner).

E-3 Mer.

R. 87

T. 143