

U. S. Department of Agriculture
FOREST SERVICE

E-8

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 27 W 5th Mer.

E. ~~one~~ sixteenth Corner common to Sections

5, and 8 brass cap

Corner consists of a Iron pipe with (not) in place


State condition Good

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species W Pine

Diameter 38"

Bearing S13°E

Distance 126 links

Do you believe this to be a genuine Land Office Corner? **yes**

If not, why? _____

J. J. Honola
(Signature)

Dec. 3 1935


Jr. Forester p-1

(Date)

(Title)

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

T. 141 N R. 27 W 54 Mer. E-8