

U. S. Department of Agriculture

FOREST SERVICE

Q-9

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 27 W 5 Mer.

S 1/16 Corner common to Sections

20, and 21

Corner consists of a Cedar Stake (~~not~~ in place)

State condition Poor

Dimensions above ground 24" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? \_\_\_\_\_

R.P.

(Signature)


Field Assistant

(Title)

5/21/35

(Date)

Metal Location Posters on a Balm  
 tree 4 inches diameter, on the  
 side of trees  
 from which this Corner bears  
 chains distant.  
 Give any further facts which will aid in finding this  
 Corner again.



(Make sketch of topography near Corner)

Mer. 0-9

5

27

R.

T. 141