

U. S. Department of Agriculture

FOREST SERVICE

H-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 27 W 5th. Mer.

S 1/16 Corner common to Sections 8 and 9

Corner consists of a Pipe with brass cap in place

State condition Good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 1/16	S 8		
N	W	S	E

S 9			
NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 1/16	
S 8	

S 1/16	
S 9	

BT

BT

Species J Pine N P J P

Diameter 12" 14" 12"

Bearing N 30° E S 0° S 47° E

Distance 15 L 150 L 26 L

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?


J. Forester Jr. (Signature)

Jan 14, 1956 (Date)

Jr. Forester P-1 (Title)

Corner again.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this



(Make sketch of topography near Corner)

Mer.

6th

R. 27W

T. 141N

H-9