

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

66-14

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 Mer. 5

1/16 Corner common to Sections

....., and 27

Corner consists of a Scribed Maple Post (not) in place
State condition Broke off at ground.

Dimensions above ground 4" x 4" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|------|--|--|
| | | | |
| | 1/16 | | |

N W S E

| | | | |
|--|--|--|--|
| | | | |
| | | | |

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Species Maple

Diameter 8"

Bearing S75°E

Distance 20 Links

Do you believe this to be a genuine Land Office Corner? No.

If not, why? Co. cor.

Raymond T. Defant

Raymond T. Defant

(Signature)

7-29-41

(Date)

Agr. Aide SP-5

(Title)

Corner again.

Give any further facts which will aid in finding this


0.15 chains distant.

from which this Corner bears due West

side of corner

tree inches diameter, on the E. side

Metal Location Poster is on a Fence post



(Make sketch of topography near Corner)

U-14 Mer.

5

R. 27

T. 141

T.