

U. S. Department of Agriculture
FOREST SERVICE

R-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 S. 5 Mer.

Sec _____ Corner common to Sections

23, 24, 25, and 26

Corner consists of a pipe (not) in place

State condition good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

Sec	Sec	Sec	Sec
23	26	25	24

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T141
R27S
S25

Sec 23
T141N
R27W

B.T.

Species cedar cedar

Diameter 6 in. 4 in.

Bearing S40E N39W

Distance 28 lks. 42 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

R. T. Derant
R. T. Derant

(Signature)

12-10-40


(Date)

J. E. [Signature]
J. E. [Signature]

(Title)

(Make sketch of topography near corner)

R-21



Metal Location Poster is on a cedar

tree 4 inches diameter, on the North

side of tree

from which this Corner bears N 30 W

4 lks. distant.

Give any further facts which will aid in finding this

Corner again.

Blazes all around corner

Corner is 72 lks. N. of line

Post 7 lks N. of pipe