

U. S. Department of Agriculture
FOREST SERVICE

A-25
SECTION
E-225
R.M. 10
M.A.

Chipewyan NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141-142 R. 26-27 5th Mer.

140 Sec. Corner common to Sections

36, 31, 6, and 1

Corner consists of a Iron Pipe (not) in place
State condition Good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species Jack Pine

Diameter 8" D.B.H.

Bearing N.E. of Corner

Distance 3 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

N. F. Shaw

(Signature)


Engineer

(Title)

Mar. 15, 35
(Date)

side of
from which this Corner bears
chains distant.
Give any further facts which will aid in finding this
Corner again.

Metal Location Poster is on a *Fence Post*
tree ~~inches diameter~~, on the *Near Stake*



(Make sketch of topography near Corner)

T. 141 R. 26-27 S. 5th Mer. A-25