

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

*Posted A-11-12
 12/11/40*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

M.C. Corner common to Sections

4, and 33

Corner consists of a brass cap ~~rod~~ in place

State condition good

Dimensions above ground 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 33		S 4	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

M.C.
 T141N
 R27W
 M.C.

M.C.
 T141N
 R27W
 M.C.

B.T.

B.T.

Species Tam. Ceder

Diameter 6" 12"

Bearing N88°W S80°W

Distance 4.52 4.58

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

R. T. Defant
 Raymond T. Defant
 (Signature)

8/22/40
 (Date)

Jr. Civil Engineer
 (Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

4.58

from which this Corner bears

N 80° E


side of

tree 12 inches diameter, on the

N. E. C.

Metal Location Poster is on a

order - B.T.



(Make sketch of topography near Corner)