

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST ^{Partial} 2-1

CORNERS OF THE PUBLIC SURVEY

T. 171N R29E20W 5th Mer.

Township Corner common to Sections
31, and 36

Corner consists of a Iron pipe cap (not) in place


State condition Good

Dimensions above ground 7 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Apparently set by County Engineer

Arthur J. Johnson

(Signature)

12/15/37

(Date)

Semi-Shellal Walker

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *S 73° E*

side of *Tree*

tree *6* inches diameter, on the *Southeast*

Metal Location Poster is on a *Red pins*



(Make sketch of topography near Corner)

2-1

T/171N. R 22430W. 574 Mer.