

U. S. Department of Agriculture

FOREST SERVICE

Pasted V-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 191N R. 29430W 5th Mer.

Section Corner common to Sections

25, 26, 30, and 31

Corner consists of a Iron pipe cap (not) in place

State condition Good

Dimensions above ground 10 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? Apparently set by County Engineer

Peter J. Johnson

(Signature)


12/15/37 (Date)

Samuel Thilled member (Title)

V-1

Corner again.

Give any further facts which will aid in finding this  
 chains distant.  
 from which this Corner bears  
 side of  
 tree inches diameter, on the  
 Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 191N. R. 29E30W. 374 Mer. V-1