

U. S. Department of Agriculture
FOREST SERVICE

Posted N-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141N* R. *29W* *5th* Mer.

44 Corner common to Sections

18, and *19*

Corner consists of a *Brass plate* (not) in place

State condition *stake pulled up by grader.*

Dimensions above ground *2 1/2" dia.* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

H. H. H. H.
(Signature)

ENGINEER


(Title)

3/22/35
(Date)

N-3

Corner again.

Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a *NONE*



(Make sketch of topography near Corner)

T. LAIN R. 29W
 5-14
 Mer. N-3