

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

V-5

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 29W 5th Mer.

Section

Corner common to Sections

29, 30, 31, and 32

Corner consists of a Scrubbed Post (not) in place

State condition Fair

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

S 30	S 31	S 32	S 39
---------	---------	---------	---------

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Tree and Distances in Links.

FOND			
	64		B.T

Species 10-8 *Q* Tamarack

Diameter 6"

Bearing S 60 W

Distance 81 k s

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? \_\_\_\_\_

*Arthur J. Johnson*  
(Signature)  
*Leslie Shelled Necker*  
(Title)

*12/20/37*  
(Date)

V-5


lines are cut all ways from this corner.  
Corner again.

Give any further facts which will aid in finding this chains distant.

From which this Corner bears side of

tree inches diameter, on the

Metal Location, Poster is on a



(Make sketch of topography near Corner)

Mer.

5th

R. 21W

T. 19N

V-5