

U. S. Department of Agriculture  
FOREST SERVICE

120  
7-27-37  
020

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N* R. *29 W* *5<sup>th</sup>* Mer.

*NE 1/4* Corner common to Sections  
*23*, \_\_\_\_\_, and \_\_\_\_\_



Corner consists of a *"I.M. with brass cap"* (not) in place  
State condition *Good*

Dimensions above ground *15"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Carl Steadland*

(Signature)

*July 27, 1936*

(Date)

*Carl Steadland*

(Title)

Corner again.

Give any further facts which will aid in finding this

chain distant.

from which this Corner bears

side of

tree 5 inches diameter, on the

Metal Location Poster is on a *Logan*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer.

R. 29

T. 141

0-20