

Form 874-0—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

*Chippewa* NATIONAL FOREST *J-7*

CORNERS OF THE PUBLIC SURVEY

T. *141* R. *29* S. *5* Mer.

Corner common to Sections *8*, and *17*

Corner consists of a *4-lb Brass Cap* (not) in place  
 State condition *Good*

Dimensions above ground *10"* inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
<i>8</i>		<i>17</i>					
N	W	S	E	NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>See #17</i>			
<i>141</i>			
<i>29</i>			


Species *Aspen*  
 Diameter *14"*  
 Bearing *S. 35° W*  
 Distance *23.665*

Do you believe this to be a genuine Land Office Corner? *Yes*  
 If not, why? \_\_\_\_\_

*P. G. McEachern*  
*3/29/35* (Date) *Assistant* (Title) *J-7*

Section 17  
Section 8

Metal Location Poster is on a tree 14 inches diameter, on the side of from which this Corner bears 135° E. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)