

U. S. Department of Agriculture-
FOREST SERVICE

Forest N-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141N* R. *29W* *5th* Mer.



Sec. Corner common to Sections
17, 16, 21, and *20*

Corner consists of a *Brass plate* (not) in place
State condition *O.K.*

Dimensions above ground *2 1/2" dia.* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

H. M. ...
(Signature)
ENGINEER
(Title) *N-9*

3/25/35
(Date)

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of tree

tree 10 inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 191N R. 29W

5+5

Mer.

N-9